

Figure 4. Figure of Impacted Wildlife Management Area and Sample Locations.

It should be noted that the impacted zone is identified as critical habitat for the Piping Plover, a threatened species, by U.S. Army Corps of Engineers and U.S. Fish and Wildlife Service.

Simple ID SSO1-042513

Diesel konge 3 USACE Land
Orl Kange

5563-060513 55MD-060513 Oll range

> 5506-660513 vel sange

5505 - 060513 od range

SS06~0506/3 DR0